


4


For correct vertical alignment the table has 4 pre-drilled holes in the underside. Use these holes when screwing the treadle to the tabletop.

Diagram shows the correct vertical alignment of the machine's balance wheel, drive belt and treadle wheel.



!


Important note about treadles with wooden legs



Upper fixing point

The upper fixing and lower fixing points are **NOT** the same.

The upper fixing points have a **large spacer washer** fitted between metal frame and **INSIDE** of wooden leg



Lower fixing point